

# Total Quality Consulting, Inc.

PO Box 969  
Whitefish, MT 59937  
(406) 862-8023

## Labor In Progress Report

Printed on 10/19/2007 at 12:31:17PM

Labor in Progress Page : 1

R.O. #	Operation	Description	Time	Charge
<b>CODY MASTERSON</b>				
0006355	COM017	T	0.00	\$0.00
0006355	COM016	CUSTOMER REPORTS...CYLINDER HEAD GASKET	0.00	\$0.00
0006355	DIA010	INSPECT AND ADVISE. FOUND THE VALVE	0.30	\$21.60
0006355	ENG519	ADJUST VALVES;	1.30	\$93.60
0006355	MIS501	PRESSURE WASH ENGINE;	0.50	\$36.00
0006362	COM017	T	0.00	\$0.00
0006362	OPT504	INSTALL REAR AIR BAG LIFT KIT;	4.00	\$288.00
		<b>Subtotal :</b>	<b>6.10</b>	<b>\$439.20</b>
<b>DON LAWHEAD</b>				
0006289	COM017	T	0.00	\$0.00
0006289	COM016	CUSTOMER REPORTS...THE VEHICLE WILL	0.00	\$0.00
0006289	DIA501	CHECK FOR NO START AS DESCRIBED.	1.50	\$108.00
0006337	COM017	T	0.00	\$0.00
0006337	COM016	CUSTOMER REPORTS...ENGINE INTERMITENTLY	0.00	\$0.00
0006337	DIA010	INSPECT AND ADVISE...	1.50	\$108.00
0006364	COM017	T	0.00	\$0.00
0006364	COM016	CUSTOMER REPORTS...THE CHECK ENGINE	0.00	\$0.00
0006364	DIA503	CHECK RUNABILITY CONCERN; ROAD	1.50	\$108.00
0006364	COM016	CUSTOMER REPORTS...THE VEHICLE SMOKES	0.00	\$0.00
0006364	DIA500	DIAGNOSE AND ADVISE.	1.00	\$72.00
0006364	ENG506	PERFORM COMPRESSION TEST;	1.00	\$72.00
0006364	COL025	WATER PUMP, REPLACE;	5.50	\$396.00
0006370	ACB010	SERPENTINE BELT, RENEW	0.50	\$36.00
0006370	ELE	REMOVE & REPLACE STARTER	1.00	\$72.00
0006370	MAN501	POWER STEERING SYSTEM FLUSH;	0.70	\$50.40
0006370	EXH005	REPLACE MUFFLER, EXHAUST PIPE, & TAIL	0.80	\$57.60
		<b>Subtotal :</b>	<b>15.00</b>	<b>\$1,080.00</b>
<b>Not found</b>				
0006364	MAN500	PERFORM 90,000 MI (144,000 KM) SERVICE	1.90	\$136.80
		<b>Subtotal :</b>	<b>1.90</b>	<b>\$136.80</b>
		<b>Total :</b>	<b>23.00</b>	<b>\$1,656.00</b>